

Cof Cof

# IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)		
	:	Examiner: Thomas M. Dougherty	
KIYOSHI NITTO	)		
A1 N 10/612 152	:	Group Art Unit: 2834	
Appl. No.: 10/612,152	)	Confirmation No. 4113	
Filed: July 3, 2003	)	Commination No. 4113	
For: VIBRATION TYPE DRIVE UNIT	: )		
U.S. Patent No.: 7,015,623 B2	:		
Issued: March 21, 2006	;	July 10, 2006 Certific	
Commissioner for Patents		July 10, 2006  Certifical  of Correction	ite Os
P.O. Box 1450		Correct	-0
Alexandria, VA 22313-1450			)

## **CERTIFICATE OF CORRECTION UNDER RULE 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

07/12/2006 RMEBRAHT 00000024 7015623

01 FC:1811

100.00 BP

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl Attorney for Patentee Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

7,015,623 B2

DATED

March 21, 2006

INVENTOR(S) :

KIYOSHI NITTO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 3:

Line 3, "characteristics" should read -- the characteristics--.

Line 19, "characteristics" should read -- the characteristics--.

Line 32, "characteristics" should read -- the characteristics--.

### COLUMN 4:

Line 64, "method that" should read --method wherein--.

Line 65, "thought." should read --contemplated.--.

## COLUMN 5:

Line 18, "that fixing" should read --in which fixing--.

Line 25, "thought" should read --contemplated --.

# COLUMN 6:

Line 63, "shape is that" should read --shape is such that--.

#### COLUMN 7:

Line 11, "13B," should read --13B demonstrates,--.

Line 20, "the shape" should read -- the design--.

Line 22, "shape that" should read -- shape such that--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

(212) 218-2100 - Telephone


(212) 218-2200 - Facsimile

(Form#30)

Form PTO 1050 (Rev. 3-82)

PATENT NO. 7,015,623 B2

No. of add'l. copies @ 30¢ per page



# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO.

7,015,623 B2

**DATED** 

March 21, 2006

INVENTOR(S) :

KIYOSHI NITTO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 3:

Line 3, "characteristics" should read -- the characteristics--.

Line 19, "characteristics" should read -- the characteristics--.

Line 32, "characteristics" should read -- the characteristics--.

### COLUMN 4:

Line 64, "method that" should read --method wherein--.

Line 65, "thought." should read --contemplated.--.

## COLUMN 5:

Line 18, "that fixing" should read --in which fixing--.

Line 25, "thought" should read --contemplated--.

# COLUMN 6:

Line 63, "shape is that" should read --shape is such that--.

#### COLUMN 7:

Line 11, "13B," should read --13B demonstrates,--.

Line 20, "the shape" should read -- the design--.

Line 22, "shape that" should read --shape such that--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

JUL 13 2006

PATENT NO. 7,015,623 B2

No. of add'l. copies @ 30¢ per page

